


NOTE NO.	NOTE
1.	PARTS SHOWN DOTTED ARE BENEATH BASE.
2.	ASSOCIATED CABLES: ----- 105742 CONTROL CABLE ----- 105743 LINE CABLE ----- 106129 POWER CABLE ----- 87469 POWER CABLE ----- FILTER WIRING ----- MOTOR LEADS ----- 105744 SHIELDED POWER CABLE
3.	COLOR CODE: BK BLACK G GREEN R RED BL BLUE O ORANGE W WHITE BR BROWN P PURPLE Y YELLOW
4.	STRAP WITH RM 39522; COVER WITH RM 60019 TUBING.

REVISIONS:	
B	106048 FILTER REMOVED 7-7-43
C	11-3-43 32343
D	REDRAWN 1-8-44



TOP VIEW FROM RIGHT SIDE

W.D. 2215- D 12-22-43	
WIRING DIAGRAM MODEL 14 TRANSMITTER DISTRIBUTOR XD 82FS XD 82FU	
DRAWN BY ENGR. K.A.S.	APPROVED K.A.B.
TELETYPE CORPORATION	